

Basic Calibration Steps

Follow the steps for successful Calibration!

1

Check the Manual

Every GDA product comes with a manual where you can find the calibration procedure section.



2

Have the right Equipment

- Gas bottle
- Tube
- Gas cap
- Digital Multimeter
- Others...

3

Zero point calibration




- Apply appropriate calibration gas
- Wait until output is stable
- Perform zero calibration
- Remove gas



4

Span point Calibration



- Apply appropriate calibration gas
- Wait until output is stable
- Perform span calibration
- Remove gas

5

Prepare Documentation

Record Calibration details and schedule for future maintenance.

